

TOLLAND COUNTY
STAFFORD, CONNECTICUT

CRYSTAL LAKE DAM
CT-00341

NATIONAL DAM INSPECTION PROGRAM
CORPS OF ENGINEERS

ENGINEERING
PLANNING
ARCHITECTURE



20 Alexander Drive, P.O. Box 767, Wallingford, CT 06492 (203) 265-6741

Civil Engineering
Construction Administration
Construction Inspection
Disaster Recovery
Electrical Engineering
Energy Engineering
Environmental Engineering
Environmental Planning
Flood Control
Forensic Services
Geotechnical Services
Mechanical Engineering
Site Development
Solid Waste Management
Storm Drainage
Structural Engineering
Surveying & Mapping
Transportation
Water Resources

June 2, 1981

Mr. Joseph B. Fryar
Department of the Army
New England Division
Corps of Engineers
424 Trapelo Road
Waltham, MA 02154

RE: Contract No. DACW 33-80-C-0052
Crystal Lake Dam (CT 00341)
CI 27 785 KH

Dear Mr. Fryar:

Our investigation of Crystal Lake Dam indicates that it is a low hazard dam. Attached is an inspection report based on work completed as of June, 1981, when all work on the project was stopped.

The following work has been completed:

1. Data Collection
2. Field Inspection
3. Geotechnical Evaluation
4. Hydraulic/Hydrologic Evaluation
5. Inspection Checklist
6. Project Sketch

Included with the attached inspection report are the national inventory forms, visual inspection checklist, sketch, hydraulic/hydrologic computations, and photo negatives for your file.

If you have any questions, please feel free to contact me.

Very truly yours,

CAHN, INC.

A handwritten signature in black ink, appearing to read "Peter M. Heynen".

Peter M. Heynen

Peter M. Heynen, P.E.

Chief Geotechnical Engineer

PMH:awp
Attachment

LOW HAZARD
PHASE I INSPECTION REPORT
NATIONAL PROGRAM OF INSPECTION OF DAMS

Name of Dam:	<u>CRYSTAL LAKE DAM</u>
Inventory Number:	<u>CT 00341</u>
State Located:	<u>CONNECTICUT</u>
County Located:	<u>TOLLAND</u>
Town Located:	<u>STAFFORD/ELLINGTON</u>
Stream:	<u>CRYSTAL LAKE BROOK</u>
Owner:	<u>STAFFORD PRINTERS, INC.</u>
Date of Inspection:	<u>MARCH 1981</u>
Inspection Team:	<u>PETER M. HEYNEN, P.E.</u> <u>JAY A. COSTELLO</u> <u>HECTOR MORENO, P.E.</u>

Crystal Lake Dam is located on Crystal Lake Brook (Thames River Basin) in a rural area of the towns of Stafford and Ellington, Connecticut. The dam is shown on the Stafford Springs USGS Quadrangle Map, having coordinates latitude N 41° 56.7' and longitude W 72° 22.5'. The dam has a drainage area of 2.8 square miles and a maximum impoundment capacity to the top of the dam of 1450 acre-feet.

Crystal Lake Dam is a 250 foot long earth embankment with a stone masonry spillway section at the central part of the dam. The dam is estimated to have been built around 1900 to raise the level of the lake. The present owner, Stafford Printers Inc. of Stafford, Connecticut, acquired the dam with property purchased from the Rhode Island Worcester Mills, in the early 1950's. Conklin Road extends across the top of the embankment and a concrete bridge extends across the spillway.

The top of the dam is 23 feet wide, is paved with asphalt for Conklin Road, and has an approximate elevation of 639.5. The highest section of the dam is about 11 feet at the dry-laid stone masonry spillway section. The spillway crest is 18.5 feet long, 3.5 feet below the top of the dam and 2 feet below the low chord of the bridge. The concrete abutments for the bridge provide side walls for the spillway weir and headwalls at the spillway approach. The outlet is a pipe of unknown type or size, which outlets at the right side of the spillway structure. The intake appears to be a concrete drop inlet structure with a trash rack located at the upstream side of the right bridge abutment.

Based on the visual inspection, the project appears to be in fair condition. The following features which could influence the future condition and/or stability were identified.

1. The concrete and trash rack at the intake structure are in poor condition and need repair.
2. There is no riprap or vegetation along the upstream slope of the embankment to protect against erosion and sloughing resulting from wave action and runoff.
3. The sides of the spillway discharge channel are eroding, possibly undermining the stone wall in this area.

The owner should retain the services of a registered professional engineer, qualified in dam design and inspection, to perform services pertaining to the following items. The engineer should establish corrective measures which should then be implemented by the owner.

1. An attempt should be made to inspect the dam during a period of low flow, so a more detailed inspection of the stone spillway structure can be made. Also, the condition of the outlet pipe and intake should be investigated, including operation of the outlet valve.
2. Riprap protection should be placed on the upstream slope between expected high and low water elevations and a grass cover established between the riprap and top of dam. Riprap should also be placed along the banks of the spillway discharge channel to prevent erosion in this area.
3. Large trees should be removed from the dam and within 10 feet of the toe of the dam.
4. Spalling of concrete at the intake structure and bridge abutments should be repaired.

Also, the owner should initiate a formal program of operation and maintenance procedures, including a monthly inspection by the owner or owner representative and proper documentation to provide accurate records for future reference. A comprehensive program of inspection by a registered professional engineer qualified in dam design and inspection should be instituted on a biennial basis.

VISUAL INSPECTION CHECK LIST

PARTY ORGANIZATION

PROJECT CRYSTAL LAKE DAMDATE: MARCH 1981TIME: 2:00 PMWEATHER: SUNNY, 50°FW.S. ELEV. 630.2 U.S. DN.SPARTY:INITIALS:DISCIPLINE:

- | | | |
|---------------------------|------------|------------------------|
| 1. <u>PETER M. HEYNEN</u> | <u>PMH</u> | <u>CAHN INC - GEO.</u> |
| 2. <u>HECTOR MORENO</u> | <u>HM</u> | <u>CAHN INC - H/H</u> |
| 3. <u>JAY A. COSTELLO</u> | <u>JAC</u> | <u>CAHN INC - GEO.</u> |
| 4. _____ | _____ | _____ |
| 5. _____ | _____ | _____ |
| 6. _____ | _____ | _____ |

PROJECT FEATUREINSPECTED BYREMARKS

- | | | |
|--------------------------|---------------------|------------|
| 1. <u>DAM EMBANKMENT</u> | <u>PMH, JAC, HM</u> | <u>A-2</u> |
| 2. <u>SPILLWAY WEIR</u> | <u>PMH, JAC, HM</u> | <u>A-3</u> |
| 3. _____ | _____ | _____ |
| 4. _____ | _____ | _____ |
| 5. _____ | _____ | _____ |
| 6. _____ | _____ | _____ |
| 7. _____ | _____ | _____ |
| 8. _____ | _____ | _____ |
| 9. _____ | _____ | _____ |
| 10. _____ | _____ | _____ |
| 11. _____ | _____ | _____ |
| 12. _____ | _____ | _____ |

PERIODIC INSPECTION CHECK LIST

Page A-2

PROJECT CRYSTAL LAKE DAMDATE MARCH 1981PROJECT FEATURE EMBANKMENTBY PMH, JAC, HM

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	639.5±
Current Pool Elevation	636.2±
Maximum Impoundment to Date	UNKNOWN
Surface Cracks	NONE OBSERVED
Pavement Condition	GOOD
Movement or Settlement of Crest	NONE OBSERVED
Lateral Movement	
Vertical Alignment	
Horizontal Alignment	APPEARS GOOD
Condition at Abutment and at Concrete Structures	
Indications of Movement of Structural Items on Slopes	NONE
Trespassing on Slopes	SOME - 4/S SLOPE
Sloughing or Erosion of Slopes or Abutments	SLoughing AT BANKS OF SPILLWAY DISCHARGE
Rock Slope Protection-Riprap Failures	N/A
Unusual Movement or Cracking at or Near Toes	
Unusual Embankment or Downstream Seepage	
Piping or Boils	NONE OBSERVED
Foundation Drainage Features	
Toe Drains	
Instrumentation System	

PERIODIC INSPECTION CHECK LIST

Page A-3

PROJECT CRYSTAL LAKE DAMDATE MARCH 1981PROJECT FEATURE SPILLWAYBY PMH, JAC, HM

AREA EVALUATED	CONDITION
<u>OUTLET WORKS-SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	<u>DRY-LAID STONE MASONRY WITH CONCRETE BRIDGE OVER WEIR</u>
a) <u>Approach Channel</u>	<u>FAIR</u>
General Condition	
Loose Rock Overhanging Channel	
Trees Overhanging Channel	{ <u>NONE</u>
Floor of Approach Channel	<u>FLAT, SAND & GRAVEL</u>
b) <u>Weir and Training Walls</u>	<u>WEIR - STONE MASONRY WALLS - CONCRETE GOOD</u>
General Condition of Concrete	
Rust or Staining	<u>NONE OBSERVED</u>
Spalling	<u>SLIGHT</u>
Any Visible Reinforcing	
Any Seepage or Efflorescence	{ <u>NONE OBSERVED</u>
Drain Holes	
c) <u>Discharge Channel</u>	<u>POOR - EROSION & SLOUGHING OF BANKS</u>
General Condition	<u>NONE</u>
Loose Rock Overhanging Channel	<u>SOME TREES & BRUSH</u>
Trees Overhanging Channel	
Floor of Channel	<u>LOGS, DEBRIS</u>
Other Obstructions	<u>N/A</u>

PERIODIC INSPECTION CHECK LIST

Page A - 4


PROJECT CRYSTAL LAKE DAMDATE MARCH 1981PROJECT FEATURE INTAKE STRUCTUREBY JAC, PMH

AREA EVALUATED	CONDITION
<u>OUTLET WORKS-INTAKE CHANNEL AND INTAKE STRUCTURE</u>	<u>APPEARS TO BE A FLAT DROP INLET - FROZEN OVER SO HARD TO INSPECT</u>
a) <u>Approach Channel</u>	
Slope Conditions	N/A
Bottom Conditions	FLAT, SAND & GRAVEL
Rock Slides or Falls	
Log Boom	
Debris	{ N/A
Condition of Concrete Lining	
Drains or Weep Holes	
b) <u>Intake Structure</u>	
Condition of Concrete	POOR - SPALLING & DETERIOR-
Stop Logs and Slots	ATION OF CONCRETE, SOME REINFORCING SHOWING TRASHRACK - METAL, POOR CONDITION, BENT, RUSTING




OVERVIEW PHOTO
(MARCH 1981)

US ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	<u>CRYSTAL LAKE DAM</u> <u>CRYSTAL LAKE BROOK</u>	STAFFORD/ELLINGTON CONNECTICUT	DATE JUNE, '81 CE # 27785KH PAGE _____
CAHN ENGINEERS INC. WALLINGFORD, CONN. ENGINEER				



View of bridge, spillway and intake from upstream side of dam (March 1981).



View of dry-laid stone masonry at spillway from right side of discharge channel (March 1981).

US ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

CAHN ENGINEERS INC.
WALLINGFORD, CONN.
ENGINEER

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

CRYSTAL LAKE DAM
CRYSTAL LAKE BROOK
STAFFORD/ELLINGTON, CT
CE # 27785 K.H
DATE JUNE '81 PAGE C-1

Project INSPECTION OF NON FEDERAL DAMS IN NEW ENGLAND Sheet 1 of 3
 Computed By Hell Checked By _____ Date 5/8/81
 Field Book Ref. _____ Other Refs. CE# 27-780-HC Revisions _____

CRYSTAL LAKE DAM, STAFFORD, CT

TENTATIVE DOWNSTREAM FAILURE HAZARD ANALYSIS

1) POTENTIAL IMPACT AREA.

REACH OF CRYSTAL LAKE BROOK (\pm) 3000' TO 5000' DS FROM
 DAM WITH 6 HOUSES WITH FIRST FLOOR ELEVATIONS RANGING
 FROM $14.3.8'$ TO $14.5.3'$ ABOVE STREAM. (\pm) 10,000' DS ONE HOUSE
 IS BEHIND A LOW DIKE (\pm) 2' ABOVE THE WL. OF A SMALL POND
 FORMED BY A MASONRY DAM WITH (\pm) 60' LONG SPILLWAY.

2) FAILURE @ CRYSTAL LAKE DAM.

ASSUME SURCHARGE TO TOP OF DAM. FIRST PT. OF OVERFLOW EL. 639.5' NAD

a) MAX. HEIGHT OF DAM: $H_{MAX} \approx 10.9'$ ($639.5 - 628.6$)

b) MID-HEIGHT LENGTH: $L \approx 40'$

c) BREACH WIDTH: $W = 0.4 \times 40 = 16'$ ASSUME $W_b = \underline{16'}$

d) ASSUMED WATER DEPTH AT TIME OF FAILURE: $y_0 \approx \underline{10.9'}$

e) SPWY DISCHARGE AT TIME OF FAILURE

CULVERT FLOWING FULL ($Box = 2'' \times 18.5'' \times 23''$);
 INV. ELEV 636' NAD. $H/D = 3.5/2 = 1.75 > 1.2$ to 1.5 - Full Flow

CULVERT GEOMETRIC PARAMETERS: $A = 37^{SOFT}$ $K = 2860$ (For $n = 0.018$)
 $L = 23'$

$Q_s = 225 H_*^{0.5}$ FOR $H_* = 3.5 - 1 = 2.5'$ $Q_s = \underline{350} \text{ cfs}$

Cahn Engineers Inc.

Consulting Engineers

Project Non-FED. DAMS INSPECTION

Sheet 2 of 3

Computed By Hill

Checked By _____

Date 5/8/81

Field Book Ref. _____

Other Refs. CE #27-785-HC

Revisions _____

f) BREACH OUTFLOW

$$Q_b = \frac{8}{27} W_b \sqrt{g} Y_0^{3/2} = \underline{\underline{970 \text{ cfs}}}$$

g) PEAK FAILURE OUTFLOW:

$$Q_p = 350 + 970 = \underline{\underline{1320 \text{ cfs}}} \quad (\text{ASSUME FULL CHANNEL (SPRAY) OUTFLOW IN ADDITION TO BREACH FLOW})$$

3) FLOOD DEPTH IMMEDIATELY % from Dam

$$Y = 0.44 Y_0 = 4.8'$$

4) ESTIMATE OF % FAILURE CONDITIONS AT POTENTIAL IMPACT AREA.

a) THE CHANNEL OF CRYSTAL LAKE BROOK % FROM THE DAM IS APPROXIMATELY TRAPEZOIDAL WITH (1) 20' BASE AND (2) 60" AND 30" TO 1" SIDE SLOPES. THE AVERAGE SLOPE OF THE CHANNEL TO THE REACH (% 3000') IS CONSIDERED TO BE THE POTENTIAL INITIAL IMPACT AREA IS (% 0.2%). (ASSUME n=0.050 FOR THE CHANNEL AT FLOOD STAGE)

b) RESERVOIR STORAGE AT TIME OF FAILURE,

ELEVATION (FT-NGVD)	AREA (ACRE)	AVE. AREA (ACR)	INCR. STOR. (ACR-FT)	STORAGE (ACR-FT)
636	179			740 *
(639.5)	(219)	202	810	(1450)
640	225			1550

*STORAGE TO FLOWLINE ASSUMED $S \geq 0.56 A H = 0.56 \times 179 \times 7.4 = 740 \text{ KFT}$
(H TO FLOWLINE = 7.4')

Cahn Engineers Inc.

Consulting Engineers

Project New-FED DAMS INSPECTION

Sheet 3 of 3

Computed By Hill

Checked By _____

Date 5/12/81

Field Book Ref. _____

Other Refs. CE #27-785-HC

Revisions _____

c) APPROXIMATE STAGE AT POTENTIAL IMPACT AREA:

$$Q_p = 1320 \text{ CFS} : Y_1 = 3.6' ; *V_1 = 44.7 \text{ ACFT} ; Q_{P_2} = 1280 \text{ CFS} ; Y_2 = 3.5' \\ V_2 = 43.5 \text{ ACFT} ; \bar{V} = 44.1 \text{ ACFT} : Q_{P_3} = 1280 \text{ CFS} ; Y_3 = 3.5' \\ \therefore Q_p = \underline{1280 \text{ CFS}} ; Y_3 = \underline{3.5'} *(\pm) 3000' \text{ DL FROM DAM}$$

d) APPROXIMATE STAGE BEFORE FAILURE

$$Q_s = 350 \text{ CFS} : Y_s = \underline{2.1'}$$

e) RAISE IN STAGE % FROM CRYSTAL LAKE DAM: $\Delta Y = \underline{1.4'}$

III) CLASSIFICATION OF DAM ACCORDING TO NED-ACE GUIDELINES:

a) SIZE: STORAGE (MAX) $\geq 1450 \text{ ACFT}$ ($1000 \leq S \leq 50000 \text{ ACFT}$)
HEIGHT (MAX) $\geq 10.9'$ ($H \leq 25 \text{ FT}$)


\therefore SIZE CLASSIFICATION: INTERMEDIATE

b) HAZARD POTENTIAL: As a result of the D/F failure analysis and in view of the impact that failure of Crystal Lake Dam may have on the potential impact area (p.1). The dam is classified as having:

HAZARD CLASSIFICATION: LOW


CRYSTAL LAKE DAM

(1) HILL & RD 4/29/81




CRYSTAL LAKE DAM

(2) HILL & RD 4/29/81



NOTE U/S SPILLWAY OPENING (\pm) THE SAME AS ABOVE EXCEPT JT JS (\pm) 2.8' HIGH (BOTTOM \pm 1.2' BELOW WL) i.e. APPROXIMATE CHANNEL DROPS \pm 1' IN THE (\pm) 23' WIDTH OF THE BRIDGE / OPENING. - TOP OF THE U/S BRIDGE CURB IS (\pm) 2.3' ABOVE LOW CHORD (SOFFIT OF SPWY. OPENING)





See reverse side for instructions.

[2] [3] [4] [5] [6] [7] [8]

[9]

[10]

[11]

[12]

IDENTIFICATION	DIVISION	STATE	COUNTY	CONGR DIST	STATE	COUNTY	CONGR DIST	NAME			LATITUDE (North)	LONGITUDE (West)	REPORT DATE
	8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80	• / • /	DAY MO YR										
	NED	DCT	01	302				CRYSTAL LAKE DAM	41 5 6 7 7 2 2 2 5 3 1 JUN 81 0				

[13]

[14]

IDENTIFICATION (Continued)	POPULAR NAME																												NAME OF IMPOUNDMENT																												
	8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80																																																								
																													CRYSTAL LAKE	1																											

[15]

[16]

[17]

[18]

[19]

[20]

LOCATION	REGION	BASIN	RIVER OR STREAM																												NEAREST DOWNSTREAM CITY - TOWN - VILLAGE																												DIST. FROM DAM (mi)	POPULATION
	8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80																																																											
	CRYSTAL LAKE BROOK																												WEST STAFFORD																													1500 ²		

[21]

[22]

[23]

[24]

[25]

[26]

[27]

[27A]

[27B]

[27C]

[27D]

[27E]

[27F]

STATISTICS	TYPE OF DAM												YEAR COMPLETED	PURPOSES												STRUCTURAL HEIGHT (ft)	HYDRAULIC HEIGHT (ft)	IMPOUNDING CAPACITIES												CORPS ENGR. DIST.	OWN. FED. R. PRV/FED SCS A.	VERIFICATION DATE			BLANK
	8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80													MAXIMUM (acre - ft.)	NORMAL (acre - ft.)	DA	MO	YR																											
	RE	OT	1900R												1	1	1450	740	NED	NNNN	S1	JUN	81	3																					

[28]

REMARKS	REMARKS																																																																																							
	8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80																																																																																							
	17 - ALSO REFERRED APPENDIX FOR 21 - SIDE ALONG MASONRY ON DISIDE EARTH 4/S ⁴																																																																																							

CHART III - INVENTORY OF DAMS IN THE UNITED STATES
SUPPLEMENTARY DATA

STA 1 2 3 4 5 6 7
NUMBER

CT00341

(A-1)

(A-2)

(A-3)

(A-4)

(A-5)

LOCATION	TOWN																						NED PERMIT NO.	STATE NUMBER																					FERC NO	U.S.G.S. SHEET																																	
	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80						
	STAFFORD, ELLINGTON																																																																														A

(B-1) (B-2) (B-3) (B-4) (B-5) (B-6) (B-7) (B-8) (B-9) (B-10) (B-11) (B-12)

DRAINAGE CHARACTERISTICS	DRAINAGE AREA SQ MI	FLOW DATA			CREST ELEV. M.S.L.	ABUT. ELEV. M.S.L.	USABLE STORAGE ACRE FEET	RESERVOIR AREA ACRES	FLASH BOARD HT FEET	OUTLET CONDUITS				INVERT ELEV. M.S.L.
		MIN CFS.	AVE CFS.	MAX. CFS.						NO.	SIZE			
	8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80	2.8			636	640		740		179				B

(C-1) (C-2) (C-3) (C-4) (C-5) (C-6) (C-7)

POWER DATA	GENERATION UNITS								AVERAGE ANNUAL GENERATION KW.H.	LAST GEN. YEAR	RETIRED YEAR	FORMER USE	CAPACITY FACTOR																																																												
	INSTALLED NO CAP. KW.		PLANNED NO CAP. KW.																																																																						
	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80

8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
A-5 ALSO ELLINGTON QUADRANGLE B-3 SPILLWAY CREST B-6 TOP OF DAM D

8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
--

MAP FORM 50107 Part 1

E